

Premier Auto Repair

783 West Boylston St.
Worcester, MA 01606

508.459.2155
mypremierrepair.com



Premier Automotive LOF & Safety Inspection

Customer:	John Smith	License:	65TF14
Vehicle:	2008 Pontiac Grand Prix	VIN:	2G2WP552481147696
Inspection date:	6/17/2019	Odometer:	in: 206,343- miles
Repair Order #:		Technician:	Tom Germain

**We have inspected your vehicle
with the following results:**



Tom Germain, Technician

Ok

Filters, Battery, Belts, and Radiator Hose	Observation	Action
Engine cranking	No Issues	
Warning Lights	Good	
Wiper Blades	Good	
Battery	Good Rated:685 Tested:603 <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	
Radiator Hoses	Good	
Parking Brake	Functions Properly	
Fluids, Exterior Lights	Observation	Action
Fluid Leaks	Good	
Washer Solvent	Good	
Engine Oil	Good __w5w30 Oil Type Non Synthetic 5Qt. Capacity	
Marker Lights	Good	

Ok

Turn Signals	Good	
Licence Plate Lights(s)	Good	
Brake Lights	Good	
Tires, Brakes & Wheels	Observation	Action
Tire Pressure	Good 30 Factory Specification	
Brake Pads: Front	Good Front brake pads are 10mm thick. Front brake rotors look good.	
Brake Pads: Rear	Good Rear brake pads are at 6-7mm. Rotor have some hot spotting. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	
Wheel Bearings	Ok	
Tie Rods	Good	
Under Car	Observation	Action
Shocks/Struts	Good	
Ball Joints	Good	
Axle/Boots	Good	
Driveshaft / U-Joints	Good	
Warning Lights, Road Test	Observation	Action
Warning Lights	Good	
Steering	Good	
Shifting	No Issues	

Ok

Filters, Battery, Belts, and Radiator Hose

✓ Technician Notes

Fluids, Exterior Lights

✓ Fog Lights

✓ Technician Notes

Tires, Brakes & Wheels

✓ Technician Notes

Under Car

✓ Technician Notes

Warning Lights, Road Test

✓ Engine Performance

✓ Chassis

✓ Technician Notes



Your Source of Vehicle Maintenance Knowledge. For More Details Click [Here](#)

Maintenance

Filters, Battery, Belts, and Radiator Hose	Observation	Action
Air Filter	Dirty Recommend replacing engine air filter. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Replace Air Filter
Cabin Air Filter	Dirty Recommend replacing cabin air filter. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	
Fluids, Exterior Lights	Observation	Action
Transmission Fluid	Dirty	BG Transmission service
Power Steering Fluid	Dirty	BG Power Steering Flush
Engine Coolant	Good for -20 degrees	BG Cooling System Flush
Headlights	Recommend headlamp restoration service. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	
Under Car	Observation	Action
Exhaust System	Rusted <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Repair Exhaust System

Bad

Filters, Battery, Belts, and Radiator Hose	Observation	Action
Belts: Serpentine/VBelts	Cracked Recommend serpentine belt replacement. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Replace Belt
Fluids, Exterior Lights	Observation	Action
Brake Fluid	>4%	BG Brake Fluid Flush
Tires, Brakes & Wheels	Observation	Action



Your Source of Vehicle Maintenance Knowledge. For More Details Click [Here](#)

Bad

Tire Rotation	<p>Recommend replace all four tires. P225/60R16</p> <p><i>Image(s):</i></p> <p><i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i></p>	
Left Front Tire	<p>Needs Replacing 2/32</p> <p><i>Image(s):</i></p> <p><i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i></p>	Replace Tire
Right Front Tire	<p>Needs Replacing 2/32</p> <p><i>Image(s):</i></p> <p><i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i></p>	Replace Tire
Right Rear Tire	<p>Needs Replacing 3/32</p>	Replace Tire
Left Rear Tire	<p>Needs Replacing 4/32</p>	Replace Tire
Under Car	Observation	Action
Fluid Leaks	<p>Small leak</p> <p>Signs of coolant leaks near front of vehicle. Recommend pressure testing cooling system for leak diagnosis.</p> <p><i>Image(s):</i></p> <p><i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i></p>	Diagnose Leak
Sway Bar Links/Bushings	<p>Broken</p> <p>Front sway bar is broken at link connections. Recommend replacing sway bar, sway bar links and sway bar bushings.</p> <p><i>Image(s):</i></p> <p><i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i></p>	Replace sway bar bushings



Your Source of Vehicle Maintenance Knowledge. For More Details Click [Here](#)

Bad

Control Arm Bushings	Broken Left front control arm bushing had completely separated from control arm and control arm is rubbing into subframe. Recommend replacing both front lower control arms for tearing out/separating front bushing. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Replace/Repair
Brake Hoses	Leaks Right rear brake caliper is leaking. Vehicle needs right rear caliper. <i>Image(s):</i> <i>Right-hand mouse-click on link and select 'Open Link in New Tab'</i>	Replace
Warning Lights, Road Test	Observation	Action
Braking	Noisy/Squeals/Squeaks Squeal noise heard front rear brakes. Noise coming from right rear from leaking caliper.	Other
Alignment	Steering Wheel Off Center Recommend four wheel alignment after tire replacement.	Perform Alignment



Your Source of Vehicle Maintenance Knowledge. For More Details Click [Here](#)